# **C500** 001708-0552





## **Description**

Disposable protective suit in "non-woven fabric".

Composition: Polypropylene with polyethylene laminates.

### **Packaging**


Pack: 50-piece box, packed in single bags.

Carton weight: 11,5 kg. Carton size: 52×32×46 cm.

#### Sizes

Measurements for each size:

SIZES	CHEST (A)(cm)	HEIGHT (B)(cm)
S	86-94	158-166
M	94-102	166-174
L	102-110	174-182
XL	110-118	182-190
XXL	118-129	190-198
3XL	129-141	198-206





#### Certifications

This product has been manufactured in compliance with the requirements of Regulation (EU) 2016/425, classified as cat. **PPE III cat.**, and in compliance with the following regulations:

Symbol	Standard
EN 340:2003 EN ISO 13688:2013	EN 340:2003 e EN ISO 13688:2013 Protective clothing - General requirements.
EN 1149-5:2018	<b>EN 1149-5:2018</b> Protective clothing - Electrostatic properties - Part 5: Performance requirements of materials and design against the risk of accumulation of electrostatic charges.
EN 13034:2005 + A1: 2009 TYPE 6 EN ISO 13982-1: 2004/A1:2010 TYPE 5	EN 13034:2005 + A1: 2009 Protective clothing against liquid chemicals - Performance requirements for chemical protective clothing that offer limited protection against liquid chemicals (Type 6) such as level 3 sodium hydroxide (10%), level 3 sulphuric acid (30%), level 3 o-xylene and level 3 1-butanol.  EN ISO 13982-1: 2004/A1:2010 Protective clothing for use against solid particulates - Part 1: Performance requirements for chemical protective clothing providing protection to the full body against airborne solid particles (type 5 clothing) according to EN ISO 13982-2: 2004.
EN 14126:2003/AC:2004 TYPE 5-B TYPE 6-B	EN 14126:2003/AC:2004 Performance requirements and test methods for protective clothing against infectious agents: (Type 5-B and Type 6-B).
EN 1073-2:2002 Classe 1	<b>EN 1073-2:2002</b> Protective clothing against radioactive contamination - Part 2: Requirements and test methods for non-ventilated protective clothing against particulate radioactive contamination: classified as ( <b>Type 1</b> )

#### **Maintenance:**

Garment care must take place according to the following:



Do not wash



Do not bleach



Do not tumble dry



Do not iron



Do not dry clean



Flammable



Do not reuse, DISPOSABLE/SINGLE-USE